



GREEN AUCTION

LotNo	2247013	LOCATION	HAKATA-A
-------	---------	----------	----------

EXCAVATOR

147th Tender Auction 2024/11/07 ~ 2024/11/08

MAKER	SUMITOMO	YEAR	2007
MODEL	SH200-5	HOUR	11573
S/N	200A5-1562		

 DOCUMENT/書類
 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	A1-4HK1XYSS-01	
	S/N	UNKNOWN	
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	NO/なし	
	NOISE	NO/なし	
	EPA	NO/なし	
	NOTE	ARROUNF INJECTION NOZZLE OIL LEAKING MODERATELY. OIL COOLER OIL LEAKING MODERATELY. ENGINE HOOD DEFORM. 噴射ノズル回り油漏れ 中 オイルクーラー油漏れ 中 ボンネット変形	

FRONT ATTACHMENT	BOOM	TYPE	STD
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		OK	
	BLADE	-	
	PINS	BOOM	OK
		ARM	LOOSE/ガタ
BUCKET		LOOSE/ガタ	
NOTE			

CYLINDERS	BOOM	OIL LEAKING SLIGHTLY/オイル漏れ小(RIGHT SIDE)
	SWING	-
	ARM	OIL LEAKING MODERATELY/オイル漏れ中
	BUCKET	OK
	BLADE	-
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	SOMETIMES NOT VERY GOOD.
	CONTROL	OK
	NOTE	スイング 左右切れが悪いときあり

ATTACHMENT	-
------------	---

REMARK

NEAR CENTER JOINT OIL LEAKING SLIGHTLY. BODY SERIAL MARK UNCLEAR. センタージョイント付近油漏れ 小 刻印不鮮明

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input type="checkbox"/> W/PAD	OK	
	600 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

CAB/CNP	CAB/CNP	LOWER FRONT GLASS BROKEN. フロント下部ガラス割損
	ROPS	NO/なし
	SEAT	OK
	CONTROL LEVER	COVER CRACKED. カバー割損
	A/C OR HEATER	OK
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	CABIN CORRODED.キャビン腐食

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませうお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました