



| | | | |
|-------|---------|----------|---------|
| LotNo | 7126003 | LOCATION | KOBE-N* |
|-------|---------|----------|---------|

| | | | | | | | |
|-------|------------|--------------|------|------------|---|------------|---|
| MAKER | mitsubishi | YEAR | 2003 | CARRIER HR | — | CARRIER KM | — |
| MODEL | FD30T | HOUR | 6709 | CASSIS S/N | — | | |
| S/N | F14C-37849 | CASSIS MODEL | — | | | | |

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

| | | | | | | | | | | | | | |
|--------------|--------------|---------|-------|-------------------|----------------|------|---------------------|----------------|---|-----------|---------------|-------------------------|--|
| ENGINE | CARRIER | CRANE | | HYDRAULIC (CRANE) | PUMP | OK | TYPE OF OUTRIGGER | — | ELECTRICAL | LIGHT | — | | |
| | MODEL | — | | | MAIN WINCH | — | OUTRIGGER CYLINDER | — | | WIPER | — | | |
| | S/N | — | | | AUX WINCH | — | OUTRIGGER EXTENSION | — | | HEATER | — | | |
| | COOLANT | OK | — | | BOOM EXTENSION | — | SWING | — | | A/C | — | | |
| | OIL | OK | — | | BOOM HOIST | — | CONTROL LEVER | OK | | BATTERY | OK | | |
| | START | OK | — | | NOTE | | | | | NOTE | | | |
| | BLOW-BY | NO / なし | — | | | | | | | | | | |
| | NOISE | NO / なし | — | | | | | | | | | | |
| NOTE | | | | | | | | | | | | | |
| HOOK | CAPACITY | MAIN | — (t) | SUB | — (t) | BOOM | LENGTH | — | m | FORK LIFT | TYPE | STD | |
| | NO. OF HOOK | — | | pcs | CONDITION | | — | FORK | LENGTH | | 1210 | mm | |
| | WIRE ROPE | — | | | SHEEVE | | — | | OK | | | | |
| | NOTE | | | | NOTE | | | MAST | LENGTH | | 5000 | mm | |
| TRANSMISSION | NO. OF SPEED | F | — | R | — | JIB | NO. OF SEC | — | sec | HYDRAULIC | LIFT CYLINDER | MINOR OIL LEAK / オイルにじみ | |
| | SHIFT | OK | | | CONDITON | | — | TILT CYLINDER | LEFT SIDE OIL LEAKING SLIGHTLY / 左側オイル漏れ小 | | | | |
| | OIL | OK | | | NOTE | | | HOIST CYLINDER | OK | | | | |
| | NOTE | | | | | | | NOTE | | | | | |
| CAB | CAB | OK | | SAFETY DEVICE | MONITOR | OK | | BRAKE | FOOT | OK | | | |
| | SEAT | OK | | | AML | — | | | PARKING | OK | | | |
| | NOTE | | | | OVER WIND CUT | — | | | NOTE | | | | |
| | | | | | | | | | | REMARK | | | |

ATTENTION/ 注意 *For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました