



LotNo	1122005	LOCATION	KOBE-N
MAKER	KUBOTA	YEAR	2014
MODEL	U-30-5	HOOR	4307
S/N	72645		

DOCUMENT/書類  UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	—
	S/N	—
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	MINOR OIL LEAK / オイルにじみ

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	<input type="checkbox"/> W/PAD		
	300 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	SWING
			OK
	ARM	TYPE	STD
			OK
	PIPING	OK	
	BUCKET	TYPE	STD
			OK
	BLADE	OK	
	PINS	BOOM	OK
	ARM	OK	
	BUCKET	OK	
NOTE	BREAKER OKADAAIYON OUB302 WORKING IS OK, OIL LEAK FROM CHISEL BUSHING (SLIGHT) / プレーカーチゼルブッシュより油漏れ		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	TORN / 破れ (SLIGHT / 小)
	CONTROL LEVER	OK
	A/C OR HEATER	—
	COMPUTER	—
	MONITOR	—
	BATTERY	OK
	NOTE	ENGINE HOOD HINGE BROKEN / エンジンフードヒンジ破損

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	4WAY MULTI LEVER / 4WAYマルチレバー

ATTACHMENT	BREAKER OKADAAIYON OUB302
------------	---------------------------

REMARK	BREAKER WORKING IS OK / プレーカー動作確認済み HOUR METER ADDED / アワーメーター交換 *UOUR 582 + 3725
--------	---

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
 \*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました