



LotNo	1246008	LOCATION	KOBE-N
MAKER	KUBOTA	YEAR	2012
MODEL	U-30-5	HOOR	4255
S/N	74654		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	-	
	S/N	-	
	COOLANT	BLOW-BY FROM RADIATOR / 吹き返し	
	OIL	OK	
	START	OK	
	BLOW-BY	YES / あり (SEVERELY/大)	
	NOISE	NO / なし	
	EPA	NO / なし	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	SWING
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	OK	
	BUCKET	TYPE	STD
		OK	
	BLADE	OK	
	PINS	BOOM	OK
		ARM	OK
BUCKET		OK	
NOTE			

CYLINDERS	BOOM	MINOR OIL LEAK / オイルにじみ
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
NOTE	MINOR OIL LEAK FROM UNDER THE SWIVEL-JOINT / スイベルジョイント下部からの軽微なオイル漏れ 4WAY MULTI LEVER / 4WAYマルチレバー	

ATTACHMENT	-
------------	---

REMARK	MACHINE OVER HEAT BE CAREFUL / オーバーヒート注意
--------	--

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input checked="" type="checkbox"/> W/PAD	SOME PADS COME OFF / パッド一部剥がれ	
	300 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
NOTE			

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	-
	MONITOR	SWITCH DOES NOT WORK / モニタースイッチ不良
	BATTERY	OK
NOTE		

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました