



LotNo	1124006	LOCATION	OSAKA-S
MAKER	KUBOTA	YEAR	2013
MODEL	RX-306	HOOR	5018
S/N	14044		

DOCUMENT/書類     UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	D1703
	S/N	7DX2580
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	

FRONT ATTACHMENT	BOOM	TYPE	OFF-SET
			OK
	ARM	TYPE	STD
			OK
	PIPING		-
	BUCKET	TYPE	STD
			OK
	BLADE		OK
	PINS	BOOM	OK
		ARM	LOOSE (SLIGHT) / ガタ (小)
	BUCKET	OK	
NOTE			

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	MINOR OIL LEAK / オイルにじみ
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
NOTE	4WAY MULTI LEVER / 4WAYマルチレバー	

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	<input type="checkbox"/> W/PAD		
	<input checked="" type="checkbox"/> 300 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	TAPED / シートテープ補修
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK

0.9T ARM CRANE / クレーン付き  
SERIAL PLATE MISSING / 銘板欠損

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
\*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
\*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
\*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました