



LotNo	1122010	LOCATION	YOKOHAMA-E
MAKER	KOBELCO	YEAR	2017
MODEL	SK38UR-6	HOOR	2,641
S/N	PQ03-01233		

DOCUMENT/書類     UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	3TNV82A-BPYBU	
	S/N	F0886	
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	NO / なし	
	NOISE	NO / なし	
	EPA	NO / なし	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	OFF-SET
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	OK	
	BUCKET	TYPE	STD
		OK	
	BLADE	OK	
	PINS	BOOM	OK
		ARM	OK
BUCKET		OK	
NOTE			

CYLINDERS	BOOM	OK
	SWING	-
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	-
	CONTROL	OK
NOTE	4WAY MULTI/4WAYマルチ	

ATTACHMENT	HYDRAULIC BREAKER / 油圧ブレーカー
------------	-----------------------------

REMARK	0.9t ARM CRANE/0.9tアームクレーン *NEED RELEASING FEE JPY10,000 (出庫料 ¥ 10,000)
--------	--

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	<input type="checkbox"/> W/PAD	OK	
	300 mm		
	PIN BUSH	-	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
 \*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました