



LotNo	7127002	LOCATION	HAKATA-S*
-------	---------	----------	-----------

MAKER	KOMATSU	YEAR	1989				
MODEL	FD20-11	HOUR	4608	CARRIER HR	—	CARRIER KM	—
S/N	335228	CASSIS MODEL	—	CASSIS S/N	—		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE	HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	—	ELECTRICAL	LIGHT	—	
	MODEL	4D95S		—	MAIN WINCH	—	OUTRIGGER CYLINDER		—	WIPER	—
	S/N	66789		—	AUX WINCH	—	OUTRIGGER EXTENSION		—	HEATER	—
	COOLANT	OK		—	BOOM EXTENSION	—	SWING		—	A/C	—
	OIL	OK		—	BOOM HOIST	—	CONTROL LEVER		OK	BATTERY	DEFECT / 不良
	START	OK		—	NOTE					NOTE	
	BLOW-BY	NO / なし		—							
	NOISE	NO / なし		—							
	NOTE	ENGINE IS DIFFICULT TO START WHEN COLD / 冷間時にエンジンがかかりにくい WATER-PUMP : WATER LEAK SLIGHT / ウォーターポンプより冷却水にじみ									

HOOK	CAPACITY	MAIN	—	(t)	SUB	—	(t)
	NO. OF HOOK	— pcs					
	WIRE ROPE	—					
	NOTE						

BOOM	LENGTH	—	m
	CONDITION	—	
	SHEEVE	—	
	NOTE		

FORK LIFT	HYDRAULIC	TYPE	STD	
		FORK	LENGTH	1200 mm
			OK	
		MAST	LENGTH	3000 mm
	OK			
	HYDRAULIC	LIFT CYLINDER	OK	
		TILT CYLINDER	OK	
		HOIST CYLINDER	—	
NOTE				

TIRE	SIZE	F:5.50-15 R:6.00-9	
	CONDITION	OK	
SHOE	W/PAD	TYPE	—
		— mm	
PIN BUSH	—		
CARRIER ROLLER	—		
TRACK ROLLER	—		
FRONT IDLER	—		
SPROCKET	—		
NOTE			

TRANSMISSION	NO. OF SPEED	F	2	R	2
	SHIFT	OK			
	OIL	OK			
	NOTE				

JIB	NO. OF SEC	—	sec
	CONDITON	—	
	NOTE		

CAB	OK
SEAT	TORN / 破れ
NOTE	

SAFETY DEVICE	MONITOR	OK
	AML	—
	OVER WIND CUT	—
	NOTE	

BRAKE	FOOT	OK
	PARKING	OK
	NOTE	

REMARK	
--------	--

ATTENTION/ 注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました