



LotNo	2122027	LOCATION	KOBE-N
MAKER	KOMATSU	YEAR	2013
MODEL	PC210-10	HOURL	8055
S/N	451358		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	-	
	S/N	-	
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	NO / なし	
	NOISE	NO / なし	
	EPA	YES / あり	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	STD
		CRACKED / 亀裂	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		-	
	BLADE	-	
	PINS	BOOM	OK
		ARM	OK
BUCKET		OK	
NOTE			

CYLINDERS	BOOM	OK
	SWING	-
	ARM	OK
	BUCKET	OK
	BLADE	-
	NOTE	

TURN TABLE	DUSTSEAL NG / ダストシール外れ
------------	------------------------

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	4WAY MULTI LEVER / 4WAYマルチレバー

ATTACHMENT	-
------------	---

REMARK	W/ REAR VIEWER CAMERA MONITOR / リアカメラ付き
--------	---

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input type="checkbox"/> W/PAD		
	600 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	YES / あり
	SEAT	WORN / 破れ
	CONTROL LEVER	OK
	A/C OR HEATER	OK
	COMPUTER	OK
	MONITOR	LCD BACKLIGHT UNSTABLE / 液晶表示不安定
	BATTERY	OK
	NOTE	

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました