



LotNo	8122007	LOCATION	OSAKA-S
MAKER	MITSUBISHI	YEAR	2007
MODEL	PA-FE73DB	HOUR	8917
S/N	FE73DB-523731	MILE	86322KM

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	—
	S/N	—
	COOLANT	OK
	OIL	NOT ENOUGH / 不足
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
NOTE	OIL LEAK / オイル漏れ	

TRANSMISSION	GEAR	OK
	SHIFT	OK
	OIL	OK
	NOTE	5M/T

HYDRAULIC	PUMP	OK
	LIFT CYLINDER	OK
	STEERING CYLINDER	OK
	NOTE	

ELECTRICAL	LIGHT	OK
	WIPER	OK
	HEATER	OK
	A/C	OK
	BATTERY	OK
	NOTE	PS, PW

CABIN/CANOPY	CAB/CNP	OK
	SEAT	OK
	CARRIER	OK
	NOTE	PW MOTOR DEFECT (PASSENGER SEAT) / パワーウィンドウ(助手席)不良

UNDERCARRIAGE	TIRE	SIZE	205/85R16
		OK	
	SHOE	TYPE	—
	<input type="checkbox"/> W/PAD	—	mm
	NOTE		

CHASSIS	CHASSIS	OK
	FRAME	OK
	VESSEL	OK
	NOTE	

BRAKE	FOOT	OK
	PARKING	OK
	RETARDER	—
	NOTE	

OTHERS	FRONT AXLE	OK
	REAR AXLE	OK
	STEERING	OK
	SUSPENSION CYLINDER	OK
	FINAL DRIVE	OK
	NOTE	

BLANK

REMARK
TADANO MANLIFT AT-121TG AUTOMATIC MOMENT LIMITER (AMC) FAILURE. OPERATION CONFIRMED IN EMERGENCY MODE / AMC 規制不良、非常操作にてブーム動作確認 EXTRA RECYCLING FEE JPY8,930 / リサイクル料

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました