



| | | | |
|-------|-------------|----------|--------|
| LotNo | 9122016 | LOCATION | KOBE-N |
| MAKER | DENYO | YEAR | 2007 |
| MODEL | DIS-130ES-C | HOUR | 1393 |
| S/N | 3785239 | MILE | - |

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

| | | |
|--------|---------|---------|
| ENGINE | MODEL | - |
| | S/N | - |
| | COOLANT | OK |
| | OIL | OK |
| | START | OK |
| | BLOW-BY | NO / なし |
| | NOISE | NO / なし |
| EPA | NO / なし | |
| NOTE | | |

| | | | |
|------------------|-----------------|---|-----|
| GENERATOR/WELDER | RATED POWER | - | KVA |
| | RATED AMPERE | - | A |
| | TERMINAL | - | |
| | CIRCUIT BREAKER | - | |
| | INSLATION | - | MΩ |
| | NOTE | | |

| | | | | | | |
|------------|-------------|-----|-----|-----------|-----|---------------------|
| COMPRESSOR | RATED PRESS | 0.7 | Mpa | RATED AIR | 3.7 | m ³ /min |
| | AIR VALVE | OK | | | | |
| | SAFTY VALVE | OK | | | | |
| | UNLOAD | OK | | | | |
| | OIL | OK | | | | |
| | NOTE | | | | | |

BLANK

| | | |
|------------|---------|----|
| ELECTRICAL | LIGHTS | - |
| | MONITOR | - |
| | SWITCH | - |
| | BATTERY | OK |
| | NOTE | |

| | | |
|-----------|------------------------------|---|
| HYDRAULIC | PUMP | - |
| | HOPPER CYLINDER | - |
| | PIVOT CYLINDER | - |
| | SCREED CYLINDER (UP/DOWN) | - |
| | SCREED CYLINDER (EXPENDABLE) | - |
| | CONTROL VALVE | - |
| NOTE | | |

| | | | |
|----------------|-------|---|---|
| IRON | WIDTH | - | m |
| | | | |
| | | | |
| EXTENSION IRON | WIDTH | - | m |
| | | | |
| SCREW(SUB) | - | | |
| NOTE | | | |

| | |
|---------|---|
| CAB/CNP | - |
| SEAT | - |
| NOTE | |

| | | | | | | |
|---------------|----------------|-------|---|----|---|---|
| UNDERCARRIAGE | TIRE | SIZE | F | - | R | - |
| | | | | | | |
| | SHOE | WIDTH | - | mm | | |
| | | | | | | |
| | PIN BUSH | - | | | | |
| | CARRIER ROLLER | - | | | | |
| | TRACK ROLLER | - | | | | |
| FRONT IDLER | - | | | | | |
| SPROCKETS | - | | | | | |
| NOTE | | | | | | |

FINISHER

| | | | | |
|-------------|---|---|---|------|
| OTHER ITEMS | | | | NOTE |
| - | - | - | - | |
| - | - | - | - | |
| - | - | - | - | |

REMARK

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました