



LotNo	9122036	LOCATION	OSAKA-S
MAKER	DENYO	YEAR	—
MODEL	DCA-150	HOURL	8013
S/N	UNKNOWN (E/G NO, EP100-T-19376) (546579)	MILE	—

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	EP100-T	GENERATOR/WELDER	RATED POWER	150	KVA	HYDRAULIC	PUMP	—	CAB/CNP	—					
	S/N	19376		RATED AMPERE	—	A		HOPPER CYLINDER	—		SEAT	—				
	COOLANT	OK		TERMINAL	OK	PIVOT CYLINDER		—	NOTE							
	OIL	OK		CIRCUIT BREAKER	OK	SCREED CYLINDER (UP/DOWN)		—								
	START	OK		INSLATION	—	MΩ		SCREED CYLINDER (EXPENDABLE)		—						
	BLOW-BY	NO / なし		NOTE		CONTROL VALVE		—								
	NOISE	NO / なし				NOTE										
	EPA	NO / なし														
NOTE	OIL LEAK / オイル漏れ															
ELECTRICAL	LIGHTS	OK	COMPRESSOR	RATED PRESS	—	Kgf/m ² Mpa	RATED AIR	—	m ³ /min	UNDERCARRIAGE	TIRE	SIZE	F	—	R	—
	MONITOR	OK		AIR VALVE	—	IRON	WIDTH	—	m		SHOE	WIDTH	—	mm		
	SWITCH	OK		SAFTY VALVE	—		EXTENSION IRON	WIDTH	—		m	PIN BUSH	—			
	BATTERY	OK		UNLOAD	—		SCREW(SUB)	—	CARRIER ROLLER		—	TRACK ROLLER	—			
	NOTE			OIL	—	NOTE		FRONT IDLER	—		SPROCKETS	—				
		NOTE		BLANK		NOTE		REMARK								

OTHER ITEMS				NOTE
—	—	—	—	
—	—	—	—	
—	—	—	—	

SERIAL PLATE MISSING / 銘板欠損
AC GENERATOR SERIAL NO. :546579

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました