



|       |         |          |             |
|-------|---------|----------|-------------|
| LotNo | 9246026 | LOCATION | YOKOHAMA-E* |
|-------|---------|----------|-------------|

|       |              |      |   |
|-------|--------------|------|---|
| MAKER | AIRMAN       | YEAR | — |
| MODEL | SDG13LAX-5B1 | HOUR | — |
| S/N   | P1DB1N0155   | MILE | — |

DOCUMENT/書類
  UNABLE TO TRAVEL(START)/不働車

|         |   |
|---------|---|
| MODEL   | D1503   |
| S/N     | 7JU1241   |
| COOLANT | NG  |
| OIL     | NG  |
| START   | NG  |
| BLOW-BY | NO / なし   |
| NOISE   | NO / なし   |
| EPA     | NO / なし   |
| NOTE    | CELL DOES NOT ROTATE DUE TO CEMENT AND SAND STAINS. / セメントや砂の汚れによりセルが回転しない。 |

|                 |   |     |
|-----------------|---|-----|
| RATED POWER     | — | KVA |
| RATED AMPERE    | — | A   |
| TERMINAL        | — |     |
| CIRCUIT BREAKER | — |     |
| INSLATION       | — | MΩ  |
| NOTE            |   |     |

|             |   |                           |           |   |                     |
|-------------|---|---------------------------|-----------|---|---------------------|
| RATED PRESS | — | Kgf/m <sup>2</sup><br>Mpa | RATED AIR | — | m <sup>3</sup> /min |
| AIR VALVE   | — |                           |           |   |                     |
| SAFTY VALVE | — |                           |           |   |                     |
| UNLOAD      | — |                           |           |   |                     |
| OIL         | — |                           |           |   |                     |
| NOTE        |   |                           |           |   |                     |

BLANK

|         |    |
|---------|----|
| LIGHTS  | NG |
| MONITOR | NG |
| SWITCH  | NG |
| BATTERY | NG |
| NOTE    |    |

|                              |   |
|------------------------------|---|
| PUMP                         | — |
| HOPPER CYLINDER              | — |
| PIVOT CYLINDER               | — |
| SCREED CYLINDER (UP/DOWN)    | — |
| SCREED CYLINDER (EXPENDABLE) | — |
| CONTROL VALVE                | — |
| NOTE                         |   |

|                |       |   |   |
|----------------|-------|---|---|
| IRON           | WIDTH | — | m |
| EXTENSION IRON | WIDTH | — | m |
| SCREW(SUB)     | —     |   |   |
| NOTE           |       |   |   |

|         |   |
|---------|---|
| CAB/CNP | — |
| SEAT    | — |
| NOTE    |   |

|                |       |      |   |   |   |
|----------------|-------|------|---|---|---|
| TIRE           | SIZE  | F    | — | R | — |
| SHOE           | WIDTH | — mm |   |   |   |
| PIN BUSH       | —     |      |   |   |   |
| CARRIER ROLLER | —     |      |   |   |   |
| TRACK ROLLER   | —     |      |   |   |   |
| FRONT IDLER    | —     |      |   |   |   |
| SPROCKETS      | —     |      |   |   |   |
| NOTE           |       |      |   |   |   |

FINISHER

| OTHER ITEMS |   |   |   | NOTE |
|-------------|---|---|---|------|
| —           | — | — | — |      |
| —           | — | — | — |      |
| —           | — | — | — |      |

REMARK

SAND STAINS, CAUTION, NEED WASHING. / 砂汚れ 洗車注意

\*NEED RELEASING FEE JPY10,000 (出庫料 ¥10,000)

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
 \*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました