



LotNo	8124003	LOCATION	YOKOHAMA-E*
-------	---------	----------	-------------

MAKER	MAEDA	YEAR	—				
MODEL	HF120-2	HOUR	3,567	CARRIER HR	—	CARRIER KM	—
S/N	12HF2523 (NU1220523)	CASSIS MODEL	—	CASSIS S/N	—		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE		HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	—	ELECTRICAL	LIGHT	—
	MODEL	S3L2			MAIN WINCH	—	OUTRIGGER CYLINDER	—		WIPER	—
	S/N	E231NKB			AUX WINCH	—	OUTRIGGER EXTENSION	—		HEATER	—
	COOLANT	OK			BOOM EXTENSION	OK	SWING	OK		A/C	—
	OIL	OK			BOOM HOIST	OK	CONTROL LEVER	OK		BATTERY	DEAD / あがり
	START	OK			NOTE					NOTE	
	BLOW-BY	NO / なし									
	NOISE	NO / なし									
	NOTE	EPA									

HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)
	NO. OF HOOK	— pcs			
	WIRE ROPE	—			
	NOTE				

BOOM	LENGTH	—	m
	CONDITION	—	
	SHEEVE	—	
	NOTE		

FORK LIFT	HYDRAULIC	TYPE	—	
		FORK	LENGTH	— mm
			—	
	MAST	LENGTH	— mm	
		—		
		—		
HYDRAULIC	LIFT CYLINDER	—		
	TILT CYLINDER	—		
	HOIST CYLINDER	—		
	NOTE			

TIRE	SIZE	—	
	CONDITION	—	
SHOE	<input type="checkbox"/> W/PAD	TYPE	RUBBER
	300 mm	DAMAGE/ちぎれ	
PIN BUSH	—		
CARRIER ROLLER	OK		
TRACK ROLLER	OK		
FRONT IDLER	OK		
SPROCKET	OK		
NOTE			

TRANSMISSION	NO. OF SPEED	F	—	R	—
	SHIFT	—			
	OIL	—			
	NOTE				

JIB	NO. OF SEC	—	sec
	CONDITON	—	
	NOTE		

SAFETY DEVICE	MONITOR	—	
	AML	—	
	OVER WIND CUT	—	
	NOTE		

BRAKE	FOOT	OK
	PARKING	—
	NOTE	

REMARK	12M
	*YARD DELIVERY FEE (引渡料 JPY 60,000) *NEED RELEASING FEE (出庫料 JPY 10,000)

ATTENTION/ 注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました