



LotNo	5250001	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	KOBELCO	YEAR	1993				
MODEL	SK100CR	HOUR	3222	CARRIER HR	—	CARRIER KM	—
S/N	YW-05155	CASSIS MODEL	—	CASSIS S/N	—		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER		CRANE		HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	—	ELECTRICAL	LIGHT	—
	MODEL	4BD1	—			MAIN WINCH	OK	OUTRIGGER CYLINDER	—		WIPER	—
	S/N	—	—			AUX WINCH	—	OUTRIGGER EXTENSION	—		HEATER	—
	COOLANT	OK	—			BOOM EXTENSION	OK	SWING	OK		A/C	—
	OIL	OK	—			BOOM HOIST	OIL LEAK / オイル漏れ	CONTROL LEVER	OK		BATTERY	DEAD / あがり
	START	OK	—			NOTE	BOOM CYLINDER, NEED WRAPPING WITH ABSORBENT MAT WHEN SHIPPING ON BULK CARRIER SHIP. / 在来船輸出の場合は吸着マット設置必要 HYDRAULIC HOSE DETERIORATION / 油圧ホース劣化あり				NOTE	
	BLOW-BY	NO / なし	—									
	NOISE	NO / なし	—									
	NOTE											
HOOK	CAPACITY	MAIN	4.9 (t)	SUB	— (t)	BOOM	LENGTH	11	m	FORK LIFT	TYPE	—
	NO. OF HOOK	1		pcs	CONDITION		OK	FORK	LENGTH		—	mm
	WIRE ROPE	OK			SHEEVE		OK					
	NOTE				NOTE			MAST	LENGTH		—	mm
TRANSMISSION	NO. OF SPEED	F	—	R	—	JIB	NO. OF SEC	—	sec	HYDRAULIC	LIFT CYLINDER	—
	SHIFT	—			CONDITON		—	TILT CYLINDER	—			
	OIL	—			NOTE			HOIST CYLINDER	—			
	NOTE							NOTE				
CAB	CAB	OK			SAFETY DEVICE	MONITOR	LCD BURN / 液晶焼け		BRAKE	FOOT	—	
	SEAT	DEFECT / 破れ				AML	OK	PARKING		—		
	NOTE					OVER WIND CUT	OK	NOTE				
						NOTE						
UNDERCARRIAGE	TIRE	SIZE	—	CONDITION	—	SHOE	TYPE	RUBBER	REMARK			
							W/PAD					
							500 mm	OK				
						PIN BUSH	OK					
						CARRIER ROLLER	OK					
						TRACK ROLLER	OK					
						FRONT IDLER	OK					
						SPROCKET	OK					
						NOTE						

ATTENTION/ 注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました