



GREEN AUCTION

## EXCAVATOR

|       |         |          |        |
|-------|---------|----------|--------|
| LotNo | 2251009 | LOCATION | KOBE-N |
| MAKER | HITACHI | YEAR     | 2013   |
| MODEL | ZX120-3 | HOURL    | 5196   |
| S/N   | 92966   |          |        |

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

|        |         |         |
|--------|---------|---------|
| ENGINE | MODEL   | —       |
|        | S/N     | —       |
|        | COOLANT | OK      |
|        | OIL     | OK      |
|        | START   | OK      |
|        | BLOW-BY | NO / なし |
|        | NOISE   | NO / なし |
|        | EPA     | NO / なし |
|        | NOTE    |         |

|               |   |                        |       |
|---------------|---|------------------------|-------|
| UNDERCARRIAGE | SHOE                                      | TYPE                   | STEEL |
|               | <input checked="" type="checkbox"/> W/PAD |                        |       |
|               | 500 mm                                    | PADS COME OFF / パッド剥がれ |       |
|               | PIN BUSH                                  | OK                     |       |
|               | CARRIER ROLLER                            | OK                     |       |
|               | TRACK ROLLER                              | OK                     |       |
|               | FRONT IDLER                               | OK                     |       |
|               | SPROCKET                                  | OK                     |       |
|               | NOTE                                      |                        |       |

|                  |        |        |     |
|------------------|--------|--------|-----|
| FRONT ATTACHMENT | BOOM   | TYPE   | STD |
|                  |        | OK     |     |
|                  | ARM    | TYPE   | STD |
|                  |        | OK     |     |
|                  | PIPING | OK     |     |
|                  | BUCKET | TYPE   | STD |
|                  |        | OK     |     |
|                  | BLADE  | —      |     |
|                  | PINS   | BOOM   | OK  |
|                  |        | ARM    | OK  |
|                  |        | BUCKET | OK  |
|                  | NOTE   |        |     |

|         |               |         |  |
|---------|---------------|---------|--|
| CAB/CNP | CAB/CNP       | OK      |  |
|         | ROPS          | NO / なし |  |
|         | SEAT          | OK      |  |
|         | CONTROL LEVER | OK      |  |
|         | A/C OR HEATER | OK      |  |
|         | COMPUTER      | OK      |  |
|         | MONITOR       | OK      |  |
|         | BATTERY       | OK      |  |
|         | NOTE          |         |  |

|           |        |                         |
|-----------|--------|-------------------------|
| CYLINDERS | BOOM   | OK                      |
|           | SWING  | —                       |
|           | ARM    | OK                      |
|           | BUCKET | MINOR OIL LEAK / オイルにじみ |
|           | BLADE  | —                       |
|           | NOTE   |                         |

|            |    |
|------------|----|
| TURN TABLE | OK |
|------------|----|

|         |                |    |
|---------|----------------|----|
| CONTROL | HYDRAULIC PUMP | OK |
|         | TRAVEL         | OK |
|         | SWING          | OK |
|         | CONTROL        | OK |
|         | NOTE           |    |

|            |   |
|------------|---|
| ATTACHMENT | — |
|------------|---|

|  |
|--|
| REMARK   |
| W/ REAR VIEWER CAMERA MONITOR / リアカメラ付き<br>4WAY MULTI LEVER / 4WAYマルチレバー |

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
\*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
\*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
\*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました