



GREEN AUCTION

MANLIFT

LotNo	8251003	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	AICHI	YEAR	1992				
MODEL	RV093	HOUR	6951	CARRIER HR	—	CARRIER KM	—
S/N	336747	CASSIS MODEL	—	CASSIS S/N	—		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER		CRANE		HYDRAULIC (CRANE)	PUMP	MINOR OIL LEAK / 油にじみ		TYPE OF OUTRIGGER	—		
	MODEL	ISUZU 4JB1		—		MAIN WINCH	—		OUTRIGGER CYLINDER	—		
	S/N	765540		—		AUX WINCH	—		OUTRIGGER EXTENSION	—		
	COOLANT	OK		—		BOOM EXTENSION	OK		SWING	—		
	OIL	OK		—		BOOM HOIST	—		CONTROL LEVER	OK		
	START	OK		—		NOTE						
	BLOW-BY	NO / なし		—								
	NOISE	NO / なし		—								
NOTE												

HOOK	CAPACITY	MAIN	— (t)		SUB	— (t)	
	NO. OF HOOK	— pcs					
	WIRE ROPE	—					
	NOTE						

BOOM	LENGTH	— m	
	CONDITION	—	
	SHEEVE	—	
	NOTE		

TRANSMISSION	NO. OF SPEED	F	—		R	—	
	SHIFT	—					
	OIL	—					
	NOTE						

JIB	NO. OF SEC	— sec	
	CONDITON	—	
	NOTE		

SAFETY DEVICE	MONITOR	—	
	AML	—	
	OVER WIND CUT	—	
	NOTE		

FORK LIFT	HYDRAULIC	TYPE	—		
		FORK	LENGTH	— mm	
			—		
		MAST	LENGTH	— mm	
—					

BRAKE	FOOT	—	
	PARKING	—	
	NOTE		

UNDERCARRIAGE	TIRE	SIZE	—	
		CONDITION	—	
	SHOE	☒ W/PAD	TYPE	STEEL
		340 mm	OK	
	PIN BUSH	OK		
	CARRIER ROLLER	OK		
	TRACK ROLLER	OK		
	FRONT IDLER	OK		
SPROCKET	OK			
NOTE				

REMARK			
MAX FLOOR HEIGHT : 9.0M DECK SIZE : 3.7x1.9M MAX DECK LOADING : 900KG			

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました